

EAST Search History

EAST Search History (Prior Art)

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	9	((DIRK) near2 (GOLDSCHMIDT)).INV.	US-PGPUB; USPAT; USOCR	OR	ON	2010/10/05 16:41
L2	151	((MICHAEL) near2 (OTT)).INV.	US-PGPUB; USPAT; USOCR	OR	ON	2010/10/05 16:42
L3	60	((UWE) near2 (PAUL)).INV.	US-PGPUB; USPAT; USOCR	OR	ON	2010/10/05 16:42
L4	11	((URSULA) near2 (PICKERT)).INV.	US-PGPUB; USPAT; USOCR	OR	ON	2010/10/05 16:42
L5	15	((ECKART) near2 (SCHUMANN)).INV.	US-PGPUB; USPAT; USOCR	OR	ON	2010/10/05 16:42
L6	1	((BEATE) near2 (SEILER)).INV.	US-PGPUB; USPAT; USOCR	OR	ON	2010/10/05 16:42
L7	111	((ROBERT) near2 (SINGER)).INV.	US-PGPUB; USPAT; USOCR	OR	ON	2010/10/05 16:43
L8	27	((JAN) near2 (STEINBACH)).INV.	US-PGPUB; USPAT; USOCR	OR	ON	2010/10/05 16:43
L9	7	((ANDREAS) near2 (VOLEK)).INV.	US-PGPUB; USPAT; USOCR	OR	ON	2010/10/05 16:43
L10	363	1 or 2 or 3 or 4 or 5 or 6 or 7 or 8 or 9	US-PGPUB; USPAT; USOCR	OR	ON	2010/10/05 16:44
L11	77	10 and repair\$3	US-PGPUB; USPAT; USOCR	OR	ON	2010/10/05 16:44
L12	0	11 and (solder with constituent with heat\$3 with laser)	US-PGPUB; USPAT; USOCR	OR	ON	2010/10/05 16:45

L13	5	11 and (solder with heat\$3 with laser)	US-PGPUB; USPAT; USOCR	OR	ON	2010/10/05 16:45
L14	721	228/119.ccls.	US-PGPUB; USPAT; USOCR	OR	ON	2010/10/05 16:52
L16	196	14 and (repair\$3 near5 (turbine or (super near2 alloy) or superalloy or substrate))	US-PGPUB; USPAT; USOCR	OR	ON	2010/10/05 16:54
L17	4	16 and (solder with heat\$3 with laser)	US-PGPUB; USPAT; USOCR	OR	ON	2010/10/05 16:54

10/5/2010 6:23:01 PM

**C:\Documents and Settings\maboagye\My Documents\EAST\Workspaces
\10588024 reparing soldering method 228-210 FAOM 09-26-2008.wsp**